

Oil Field Environmental Incident Summary

Incident: 20141205105647 **Date/Time of Notice:** 12/05/2014 10:56

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: USA 153-95-4B-8-2HS

Field Name: CHARLSON

Well File #: 27208

Date Incident: 12/5/2014 **Time Incident:** 09:26

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 4

Qtr:

Location Description: Just off the north side of the well pad. About 20' long 3' wide.

Submitted By: Doug Hanson

Received By:

Contact Person: Doug Hanson

PO BOX 935

BISMARCK, ND 58502

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels	4	barrels
Brine					0	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/19/2016

Clean Up Concluded: 12/10/2014

Risk Evaluation:

none.

Areal Extent:

20' by 3' wide off the north side of the well pad.

Potential Environmental Impacts:

It will be thoroughly cleaned and there should not be any impact.

Action Taken or Planned:

Tanks volumes will be more closely monitored.

Wastes Disposal Location: Fluids put back into tanks to be recycled. Some soils will be scraped and removed to an approved landfill. PDI

Agencies Involved: BLM

Updates

Date: 12/5/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Tank overflowed and flow exited the well pad to the north. Followup is necessary.

Date: 12/10/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12/10/2014.

Spill occurred at an active drilling location. Followup is necessary in the spring to ensure proper cleanup.

More followup is necessary.

Date: 6/9/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 4.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 5:40 p.m. Sunny, 78 degrees, wind out of the NW at 15 mph. The area of concern located north of the flare pit had been scraped and leveled. All contaminated soil had been removed. No visible staining of soil could be found in the area that was cleaned up. No additional followup needed.