

# Oil Field Environmental Incident Summary

**Incident:** 20141205160449      **Date/Time of Notice:** 12/05/2014 16:04

**Responsible Party:** OXY USA INC.

**Well Operator:** OXY USA INC.

**Well Name:** WILLIAM SADOWSKY 1-4-9H-142-96

**Field Name:** MANNING

**Well File #:** 19172

**Date Incident:** 12/4/2014      **Time Incident:** 12:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 143      **Rng:** 96      **Sec:** 33      **Qtr:**

**Location Description:**

**Submitted By:** Rebecca Zent

**Received By:**

**Contact Person:** Rebecca Zent  
5 GREENWAY PLAZA STE 110  
HOUSTON, TX 77046-0506

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	6	Barrels	5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Contaminated surface material on location

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material on location

**Action Taken or Planned:**

Trucking company dispatched clean up crew and driver was disciplined

**Wastes Disposal Location:** Renewable Resources

**Agencies Involved:**

**Updates**

---

**Date:** 12/5/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.