

Oil Field Environmental Incident Summary

Incident: 20141220123037 **Date/Time of Notice:** 12/20/2014 12:30

Responsible Party: NEWFIELD PRODUCTION COMPANY

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: HOLM 150-98-5-8-10H

Field Name: SIVERSTON

Well File #: 25863

Date Incident: 12/19/2014 **Time Incident:** 23:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 98

Sec: 5

Qtr:

Location Description:

Submitted By: Tim Eaton

Received By:

Contact Person: Tim Eaton
363 N. SAM HOUSTON, PKWY E
SUITE 100
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels	15	barrels
Other						

Description of Other Released Contaminant:

None

Inspected:

Written Report Received: 1/7/2015

Clean Up Concluded: 12/22/2014

Risk Evaluation:

None, concrete soil mixture on pad.

Areal Extent:

Contained to location.

Potential Environmental Impacts:

None

Action Taken or Planned:

Water was vacuumed up then trucked for disposal.

Wastes Disposal Location: Clean Energy in Keene, ND

Agencies Involved:

Updates

Date: 12/22/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to truck overflow, remained on location according to the report. NDIC retains oversight.