

Oil Field Environmental Incident Summary

Incident: 20141224134952 **Date/Time of Notice:** 12/24/2014 13:49

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: NYGAARD 1-29

Field Name: PRONGHORN

Well File #: 8399

Date Incident: 12/20/2014 **Time Incident:** 09:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 101

Sec: 29

Qtr: NW NE

Location Description: Nygaard SWD tank Battery

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Cleanup and remediation of area will start when weather is favorable.

Wastes Disposal Location: In situ remediation of contaminated soil. Any liquids to be disposed of at SWD.

Agencies Involved:

Updates

Date: 12/26/2014 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within dike according to the report. NDIC retains oversight.