

Oil Field Environmental Incident Summary

Incident: 20141226193614 **Date/Time of Notice:** 12/26/2014 19:36
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: RINK 24-8H
Field Name: PERSHING **Well File #:** 16854
Date Incident: 12/26/2014 **Time Incident:** 13:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 149 **Rng:** 96 **Sec:** 8 **Qtr:** SW SE
Location Description: adjacent to the south east side of the well pad.

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Blowout

Release Contained in Dike: No		Reported to NRC: No	
	Spilled	Recovered	Followup
	Units	Units	Units
Oil	2		
	Barrels		
Brine			
Other			

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 1/9/2015

Risk Evaluation:
none

Areal Extent:
approximately 150 feet by 60 feet.

Potential Environmental Impacts:

none

Action Taken or Planned:

the oil impacted snow in the pasture and the oil impacted gravel on the well pad will be collected and sent for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/29/2014 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a blowout, impacted a pasture southeast of the well pad in an area approximately 150 feet by 60 feet according to the report. Followup is necessary.

Date: 12/30/2014 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 8:50 a.m. on 12/30/14. Majority of release remained on location. In the SE corner of well pad, the spray had gone over berm and off location. Impact was on snow-covered ground. Spoke with contact person and was told they were waiting for One Call to flag the area. Once area is flagged, they will begin cleanup and remove impacted area and take for proper disposal. More followup is required.

Date: 5/28/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 5/28/15, at 10:37 a.m. There does not appear to be any remaining impact from release off location. Confirmation samples were taken at this time. Further followup may be required depending on sample results.

Date: 6/11/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 2.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 12:31pm. The weather was sunny with wind out for the southeast at 15 mile/hr. The area of impact has been re-vegetated and looks good. Waiting for test results
The GPS location for site is N47.73332 & W 103.00076.

Date: 2/16/2016 **Status:** Correspondence

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Reviewed lab results. No further follow-up required.