

# Oil Field Environmental Incident Summary

**Incident:** 20150106163236      **Date/Time of Notice:** 01/06/2015 16:32

**Responsible Party:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** MARSH 6092 11-33H

**Field Name:** COTTONWOOD

**Well File #:** 21745

**Date Incident:** 1/6/2015      **Time Incident:** 09:30

**Facility ID Number:**

**County:** BURKE

**Twp:** 160

**Rng:** 92

**Sec:** 33

**Qtr:**

**Location Description:**

**Submitted By:** Tim Christianson

**Received By:**

**Contact Person:** Kaden Elwess  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

|            | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b> | 30             | Gallons      | 30               | Gallons      | 25              | gallons      |

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/16/2016

**Clean Up Concluded:** 1/7/2015

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

Light mist of oil went approximately 30 yards off of location into pasture.

**Potential Environmental Impacts:**

Limited

**Action Taken or Planned:**

Standard mist clean up

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 1/7/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 1/14/2015    **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Oil was wind blown into pasture in an approximately 30- by 100-foot swath. Impacted snow and vegetation were scraped up and disposed of. No apparent impacts to soil. No further action is warranted.