

Oil Field Environmental Incident Summary

Incident: 20150110180616 **Date/Time of Notice:** 01/10/2015 18:06

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: SNOWSHOE 30-31H

Field Name: GLASS BLUFF

Well File #: 20666

Date Incident: 1/8/2015 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 102

Sec: 30

Qtr: NW NE

Location Description: Seven miles east of Cartwright, ND on Hwy 200. Location is on the south side of the road

Submitted By: Dustin Anderson

Received By:

Contact Person: Dustin Anderson
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 15 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	40	Gallons	40	Gallons	40	gallons

Brine

Other

Description of Other Released Contaminant:

Oil

Inspected:

Written Report Received: 3/21/2016

Clean Up Concluded: 1/11/2015

Risk Evaluation:

None

Areal Extent:

1,500 square feet

Potential Environmental Impacts:

Low - snow buffered the topsoil

Action Taken or Planned:

Removed oil stained snow

Wastes Disposal Location: Secure

Agencies Involved:

Updates

Date: 1/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray of oil off location. Followup is necessary. Cause not specified. Impacted land listed as pasture. If confirmed, will need to brief State Veterinarian.