

Oil Field Environmental Incident Summary

Incident: 20150119165405 **Date/Time of Notice:** 01/19/2015 16:54

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: NESS 41-21XH CTB

Field Name: SANISH

Well File #:

Date Incident: 1/17/2015 **Time Incident:** 17:00 **Facility ID Number:** 220826-01

County: MOUNTRAIL **Twp:** 154 **Rng:** 91 **Sec:** 21 **Qtr:** NE NE

Location Description:

Submitted By: Brian Wurm

Received By:

Contact Person: Brian Wurm
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.2 Mile

Distance Nearest Water Well: 0.2 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels	30	Barrels	30	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/30/2015

Clean Up Concluded: 1/20/2015

Risk Evaluation:

None noted

Areal Extent:

Approximately 200' by 200' to south east of location.

Potential Environmental Impacts:

None noted

Action Taken or Planned:

A vac truck was brought in to pick up all free liquids and impacted material. Impacted area off location will be addressed with landowner approval.

Wastes Disposal Location: Impacted material will be taken to appropriate landfill.

Agencies Involved:

Updates

Date: 1/20/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 2/2/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 2/2/2015 16:03.

Spill appears to be cleaned up; however, there is a small stream outside of impact area. Follow up with company to have a diesel range organics (DRO) sample collected from the stream during the spring.

Followup is necessary to ensure proper cleanup.

Date: 4/24/2015 **Status:** Awaiting Documentation

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 17:45 4/6/2015.

Soil scraped up off of location. A request has been sent for water sample results from the nearby stream that may have been impacted.

Site can be closed depending on the results from the stream.

More followup is necessary.

Date: 5/18/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sample results have been sent in and show no negative impacts to the streams and wetlands to the east of the impact areas.

A No Further Action letter will be sent.

No followup is necessary.