

Oil Field Environmental Incident Summary

Incident: 20150120134942 **Date/Time of Notice:** 01/20/2015 13:49

Responsible Party: NEWFIELD PRODUCTION COMPANY

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: OLGA 150-99-15-22-1H

Field Name: SOUTH TOBACCO GARDEN

Well File #: 20737

Date Incident: 1/18/2015 **Time Incident:** 17:30

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 99

Sec: 15

Qtr: N2 N2

Location Description:

Submitted By: Tim Eaton

Received By:

Contact Person: Tim Eaton
363 N. SAM HOUSTON, PKWY E
SUITE 100
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | | | | | | |
| Brine | 15 | Barrels | 15 | Barrels | 15 | barrels |
| Other | | | | | | |

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/27/2015

Clean Up Concluded: 1/20/2015

Risk Evaluation:

All liquid remained on location.

Areal Extent:

50' x 150' on well pad

Potential Environmental Impacts:

Impact was to location soils only.

Action Taken or Planned:

The trucking company will stress to their drivers the importance of checking this valve often and securing it with a strap.

Wastes Disposal Location: Nuverra disposal facility

Agencies Involved:

Updates

Date: 1/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.