

# Oil Field Environmental Incident Summary

**Incident:** 20150123220526      **Date/Time of Notice:** 01/23/2015 22:05

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** BRADLEY ROBERT 1-12H

**Field Name:** DANEVILLE

**Well File #:** 29143

**Date Incident:** 1/23/2015      **Time Incident:** 08:45

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 161      **Rng:** 102      **Sec:** 1      **Qtr:**

**Location Description:** Lot #3

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1.4 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	1	Barrels	2	barrels
<b>Brine</b>	20	Barrels	20	Barrels	20	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/15/2016

**Clean Up Concluded:** 6/12/2016

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Repairs completed. Vacuum truck recovered oil and brine. Dikes to be flushed with fresh water and bioremediation to be completed as weather permits.

**Wastes Disposal Location:** Brine tank

**Agencies Involved:**

**Updates**

---

**Date:** 1/26/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.