

# Oil Field Environmental Incident Summary

**Incident:** 20150126114542      **Date/Time of Notice:** 01/26/2015 11:45

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** SHERVEN TRUST 153-95-27A-7HS

**Field Name:** CHARLSON

**Well File #:** 30183

**Date Incident:** 1/26/2015      **Time Incident:** 09:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 22

**Qtr:**

**Location Description:**

**Submitted By:** Derek Enderud

**Received By:**

**Contact Person:** Derek Enderud  
PO BOX 935  
BISMARCK, ND 58502

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	45	Barrels			45	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/7/2016

**Clean Up Concluded:** 1/27/2015

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Vac trucks en route, will lay oak mats down for trucks to drive on to prevent them from sinking in. Fully expect to recover amount spilled.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 1/26/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to PetroHunt personnel, this spill remained on location. NDIC retains oversight.