

# Oil Field Environmental Incident Summary

**Incident:** 20150130100341      **Date/Time of Notice:** 01/30/2015 10:03

**Responsible Party:** Running Horse

**Well Operator:** XTO ENERGY INC.

**Well Name:** FBIR WALKER 34X-25

**Field Name:** HEART BUTTE

**Well File #:** 19293

**Date Incident:** 1/29/2015      **Time Incident:** 10:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 149

**Rng:** 92

**Sec:** 25

**Qtr:** SW SE

**Location Description:**

**Submitted By:** Kaylan Dirx

**Received By:**

**Contact Person:** Josh Jacobson  
P.O Box 6501  
Englewood, CO 80155

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	80	Gallons	80	Gallons		

**Description of Other Released Contaminant:**

Diesel fuel

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None- spill was contained on location and cleaned up immediately.

**Areal Extent:**

**Potential Environmental Impacts:**

None- spill was contained on location and cleaned up immediately.

**Action Taken or Planned:**

Spotting procedures were addressed with the responsible party.

**Wastes Disposal Location:** IHD

**Agencies Involved:**

**Updates**

---

**Date:** 1/30/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.