

# Oil Field Environmental Incident Summary

**Incident:** 20150205155454      **Date/Time of Notice:** 02/05/2015 15:54  
**Responsible Party:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Operator:** FIDELITY EXPLORATION & PRODUCTION COMPANY  
**Well Name:** BARNHART1 20-17H  
**Field Name:** HEART RIVER      **Well File #:** 27394  
**Date Incident:** 2/5/2015      **Time Incident:** 09:00      **Facility ID Number:**  
**County:** STARK      **Twp:** 139      **Rng:** 97      **Sec:** 20      **Qtr:**

**Location Description:**

**Submitted By:** Edward Pottorff      **Received By:**

**Contact Person:** Edward Pottorff  
1801 CALIFORNIA STREET  
SUITE 2500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	4	Barrels	3.5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

No immediate risks were identified.

**Areal Extent:**

***Potential Environmental Impacts:***

The spill remained on the pad and only the well/facility soils were impacted.

***Action Taken or Planned:***

The contract oil hauler immediately mobilized a cleanup crew to the site and began using peat moss to absorb the spilled crude oil. The affected facility soils will then be excavated, and the peat moss and soils will temporarily be staged on heavy rolled plastic laid out in an area on the well pad while a laboratory sample is collected and analyzed for disposal purposes. An earthen berm will be constructed around the staging area and plastic sheeting will be placed over the peat moss and soil to protect it from precipitation. Once the lab results are received, the peat moss and affected soils will be hauled off site to a permitted disposal facility.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 2/6/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Espe, Brady

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to truck overflow, remained on location according to the report. NDIC retains oversight.