

Oil Field Environmental Incident Summary

Incident: 20150207182920 **Date/Time of Notice:** 02/07/2015 18:29

Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: SWENSON B 1

Field Name: PORTAL

Well File #: 5950

Date Incident: 2/7/2015

Time Incident: 13:45

Facility ID Number:

County: BURKE

Twp: 163

Rng: 91

Sec: 7

Qtr:

Location Description: Uncultivated flowline right-of-way

Submitted By: Gary Watson

Received By:

Contact Person: Galen Kalmbach
103 First Avenue NE
Mohall, ND 58761

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons	2	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Minimal impact to topsoil.

Areal Extent:

2 feet x 2 feet

Potential Environmental Impacts:

Minimal impact to topsoil.

Action Taken or Planned:

Affected topsoil will be scraped up and hauled to an approved disposal facility. Jim Potts (NDIC) has been notified. Surface owner will be notified.

Wastes Disposal Location: An approved disposal facility.

Agencies Involved:

Updates

Date: 2/9/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas along a pipeline right of way. Followup is necessary.

Date: 2/25/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call from surface landowner. According to landowner, the patch placed on pipeline is not working. The pipeline is still leaking salt water into the excavation made to originally fix the pipeline.

Date: 4/18/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 4/18/2016, at 2:06 p.m. It is difficult to determine area of release as there is no definite area of disturbance noticed. A possible area is on the east side of the lease road connecting Swenson B to Swenson B1. I used a conductivity probe to check the area, and readings were similar to background readings. More follow-up is required during growing season and to check on exact area where release occurred.