

# Oil Field Environmental Incident Summary

**Incident:** 20150210202409      **Date/Time of Notice:** 02/10/2015 20:24  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** CCU MERIWETHER CTB  
**Field Name:** CORRAL CREEK      **Well File #:**  
**Date Incident:** 2/10/2015      **Time Incident:** 18:00      **Facility ID Number:** 416647-03  
**County:** DUNN      **Twp:** 147      **Rng:** 95      **Sec:** 30      **Qtr:** NE NE  
**Location Description:** immediately adjacent to the east side of the pad.

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Pasture      **Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile  
**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Gallons				

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/19/2016      **Clean Up Concluded:** 2/13/2015

**Risk Evaluation:**

None

**Areal Extent:**

approximately 125 feet by 25 feet

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Oil impacted vegetation will be collected for appropriate disposal.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 2/11/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

---

**Date:** 2/24/2015    **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 1510. At the time of the site visit, the impacted area had been scraped up, and the impacted soils and vegetation had been disposed of. Burlington Resources was asked to collect confirmation samples and submit the results to the NDDoH.