

Oil Field Environmental Incident Summary

Incident: 20150217073650 **Date/Time of Notice:** 02/17/2015 07:36

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HELENA 4-7H

Field Name: BROOKLYN

Well File #: 29866

Date Incident: 2/16/2015 **Time Incident:** 08:00

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 98 **Sec:** 7 **Qtr:**

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other 3 Barrels

Description of Other Released Contaminant:

Fresh water with descaler chemical.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Fluid flowed from location onto well site reclaim.

Potential Environmental Impacts:

Minimal

Action Taken or Planned:

Standing fluid was sucked up using vac.

Wastes Disposal Location: TBD

Agencies Involved: Notified Tami Cook NDIC by phone on 2/16/2015 at 4:09PM CT

Updates

Date: 2/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.