

# Oil Field Environmental Incident Summary

**Incident:** 20150220141438      **Date/Time of Notice:** 02/20/2015 14:14

**Responsible Party:** Schlumberger

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** FRISCO 3-31H

**Field Name:** GLASS BLUFF

**Well File #:** 29302

**Date Incident:** 2/20/2015      **Time Incident:** 09:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152      **Rng:** 102      **Sec:** 31      **Qtr:**

**Location Description:**

**Submitted By:** Timothy Ilse

**Received By:**

**Contact Person:** Leon Koscielsk  
13959 Hwy 2 W.  
Williston, ND 58802

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	3	Barrels	3	Barrels		

**Description of Other Released Contaminant:**

Fresh water with friction reducer added.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

10 ft. by 20 ft. area

**Potential Environmental Impacts:**

Well site soil

**Action Taken or Planned:**

Water was sucked up with vac skid and placed in tank for disposal at Prairie Disposal.

**Wastes Disposal Location:** Prairie Disposal

**Agencies Involved:** Called John Axtman @ 13:15 2/20

**Updates**

---

**Date:** 2/23/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.