

# Oil Field Environmental Incident Summary

**Incident:** 20150223093401      **Date/Time of Notice:** 02/23/2015 09:34

**Responsible Party:** ENERPLUS RESOURCES USA CORPORATION

**Well Operator:** ENERPLUS RESOURCES USA CORPORATION

**Well Name:** SOFTSHELL 152-94-33C-28H TF

**Field Name:** ANTELOPE

**Well File #:** 27587

**Date Incident:** 2/22/2015      **Time Incident:** 08:35

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 94

**Sec:** 32

**Qtr:**

## Location Description:

**Submitted By:** David Van der Vieren

**Received By:**

**Contact Person:** Josh Ruffo  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None.

**Areal Extent:**

**Potential Environmental Impacts:**

None.

**Action Taken or Planned:**

Shale Oilfield Services called immediately and the spill was cleaned up.

**Wastes Disposal Location:** Approved waste facility

**Agencies Involved:** BIA, BLM, TAT

**Updates**

---

**Date:** 2/23/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.