

Oil Field Environmental Incident Summary

Incident: 20150224105949 **Date/Time of Notice:** 02/24/2015 10:59
Responsible Party: Kevin Jacob
Well Operator: WHITE OWL ENERGY SERVICES, INC
Well Name: W O Watford 1
Field Name: SIVERSTON **Well File #:** 90172
Date Incident: 2/22/2015 **Time Incident:** 17:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 98 **Sec:** 22 **Qtr:** NE SW
Location Description:

Submitted By: Kevin Jacob **Received By:**
Contact Person: Kevin Jacob
12271 26F St NW
Watford City, ND 58854

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 1000 Feet
Distance Nearest Water Well: 60 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels	20	Barrels	20	barrels
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 1/13/2017 **Clean Up Concluded:** 2/22/2015

Risk Evaluation:

Saltwater spilled into diked area. A potential fire/explosive hazard could have occurred given the right circumstances.

Areal Extent:

Potential Environmental Impacts:

Soil contamination within a diked area.

Action Taken or Planned:

The water has already been removed on 2/23/25 by use of vacuum tractor/trailer.

Wastes Disposal Location: Water was disposed of within our own saltwater disposal system.

Agencies Involved:

Updates

Date: 2/24/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.