

# Oil Field Environmental Incident Summary

**Incident:** 20150226153445      **Date/Time of Notice:** 02/26/2015 15:34  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** LILLIBRIDGE 41-27TFH-ULW  
**Field Name:** BLUE BUTTES      **Well File #:** 28346  
**Date Incident:** 2/26/2015      **Time Incident:** 02:45      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 96      **Sec:** 27      **Qtr:**  
**Location Description:** Center of east side of location down the hill into roadside ditch

**Submitted By:** Josh Gandy      **Received By:**  
**Contact Person:** Tim Homiston  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Surface Water

**Distance Nearest Occupied Building:**  
**Distance Nearest Water Well:**

**Type of Incident** Tank Overflow

<b>Release Contained in Dike</b>		<b>Reported to NRC:</b>	
<b>Spilled</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>			
<b>Brine</b>			
<b>Other</b>	40	<b>Barrels</b>	

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**  
None

**Areal Extent:**  
6ft wide stream running approximately 200 ft long

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Awareness training during water transfer operations

**Wastes Disposal Location:** N/A

**Agencies Involved:**

**Updates**

---

**Date:** 2/27/2015

**Status:** Reviewed; Followup Required

**Staff:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank overflow, got off location. Followup is necessary.