

Oil Field Environmental Incident Summary

Incident: 20150226160554 **Date/Time of Notice:** 02/26/2015 16:05
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: LILLIBRIDGE 41-27TFH-ULW
Field Name: BLUE BUTTES **Well File #:** 28346
Date Incident: 2/26/2015 **Time Incident:** 02:45 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 96 **Sec:** 27 **Qtr:**
Location Description: This is a resubmission: Fresh water only...Center of east side of location running down to roadside ditch

Submitted By: Josh Gandy **Received By:**

Contact Person: Tim Homiston
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site **Affected Medium:** Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other 40 Barrels

Description of Other Released Contaminant:

Fresh water

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

6ft wide by 200ft long

Potential Environmental Impacts:

None

Action Taken or Planned:

Personnel training

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/27/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, got off location. Followup is necessary.

Date: 3/19/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 3/19/2015.

No sign of spill or negative environmental impacts related to the reported spill.

No followup is necessary.