

# Oil Field Environmental Incident Summary

**Incident:** 20150302193429      **Date/Time of Notice:** 03/02/2015 19:34

**Responsible Party:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:** GEORGE ADAMS 22-6

**Field Name:** MOUNTROSE

**Well File #:** 10905

**Date Incident:** 3/2/2015      **Time Incident:** 08:30

**Facility ID Number:**

**County:** BOTTINEAU

**Twp:** 160

**Rng:** 82

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Gary Watson

**Received By:**

**Contact Person:** Galen Kalmbach  
103 First Avenue NE  
Mohall, ND 58761

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.8 Mile

**Distance Nearest Water Well:** 0.8 Mile

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	2	Barrels		
<b>Brine</b>	8	Barrels	8	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Minimal impact to well site soil.

**Areal Extent:**

**Potential Environmental Impacts:**

Minimal impact to well site soil.

**Action Taken or Planned:**

Scott Dilhe - NDIC inspector has been notified. Fluids will be vacuumed up. Affected soil and snow will be scraped up with application of fly ash as needed and will be hauled to an approved disposal facility.

**Wastes Disposal Location:** Approved disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 3/3/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.