

Oil Field Environmental Incident Summary

Incident: 20150303164940 **Date/Time of Notice:** 03/03/2015 16:49

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 13-26H

Field Name: PARSHALL

Well File #: 17051

Date Incident: 3/2/2015 **Time Incident:** 17:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 26

Qtr: NW NW

Location Description: The location submitted in the report is the nearest location to the incident being referenced. The pad itself where the incident occurred is the Risan Fresh Water Depot.

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Other - Described Above

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Fresh Water, snow melt and Parshall Fire Dept fire suppression water

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

Off location to the S/SW, offsite freshwater runoff is to be determined.

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Personnel were evacuated and 911 dispatched. More information and determining factors will be supplied to the agencies on completion of the investigation. This will be done verbally and using the NDIC follow up report. Adjacent landowners have been contacted.

Wastes Disposal Location:

Agencies Involved: TAT, BIA, MHA Local Fire Department

Updates

Date: 3/3/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.