

# Oil Field Environmental Incident Summary

**Incident:** 20150311112310      **Date/Time of Notice:** 03/11/2015 11:23

**Responsible Party:** Badlands Trucking

**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

**Well Name:** WOLVERINE FEDERAL 4-31-30TFH

**Field Name:** ELM TREE

**Well File #:** 21398

**Date Incident:** 3/11/2015      **Time Incident:** 03:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 93

**Sec:** 31

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Ray Gorka

**Received By:**

**Contact Person:** Ray Gorka  
1809 S BROADWAY, STE U  
(701) 839-1133  
Minot, ND 58701

**General Land Use:** Pasture

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1.9 Mile

**Distance Nearest Water Well:** 1.9 Mile

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	2.5	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

.....

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None.....

**Areal Extent:**

.....

**Potential Environmental Impacts:**

None.....Surface

**Action Taken or Planned:**

When discovered, driver stopped taking oil. Called our lease operator, contacted a vacuum truck company and a spill remediator to scrape up the impacted surface materials for proper disposal.

**Wastes Disposal Location:** Licensed disposal site for oil impacted materials...

**Agencies Involved:**

**Updates**

---

**Date:** 3/11/2015    **Status:** Reviewed - Assigned to Other Agency    **Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.