

# Oil Field Environmental Incident Summary

**Incident:** 20150317090947      **Date/Time of Notice:** 03/17/2015 09:09

**Responsible Party:** QEP ENERGY COMPANY

**Well Operator:** QEP ENERGY COMPANY

**Well Name:** MHA 8-32-29H-150-91

**Field Name:** HEART BUTTE

**Well File #:** 29717

**Date Incident:** 3/16/2015      **Time Incident:** 20:30

**Facility ID Number:**

**County:** DUNN

**Twp:** 149

**Rng:** 91

**Sec:** 5

**Qtr:** SE SW

**Location Description:** Independence Point

**Submitted By:** Jerry Reinisch

**Received By:**

**Contact Person:** Jerry Reinisch  
1050 17TH ST STE 500  
DENVER, CO 80265

**General Land Use:** Pasture

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 4.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	10	Barrels	10	Barrels		

**Description of Other Released Contaminant:**

OBM drilling mud

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

low, materials was confined to the containment.

**Areal Extent:**

**Potential Environmental Impacts:**

The tank farm on the pad is lined with a containment berm. Minimal amount of pad surface soil was impacted.

**Action Taken or Planned:**

Material was immediately squeegeed to central location and vacuumed up and placed back in the holding tank.

The impacted soil was placed with the drilling cuttings and will be transported to disposal facility for disposal. Fluid Pro hand was asked to double check alignment of valves and to walk the lines out after starting the centrifuge.

**Wastes Disposal Location:** Transported with the drilling cuttings to a disposal facility.

**Agencies Involved:** BIA Environmental. MHA Energy

**Updates**

---

**Date:** 3/17/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank overflow, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.