

Oil Field Environmental Incident Summary

Incident: 20150323101851 **Date/Time of Notice:** 03/23/2015 10:18

Responsible Party: BOH Trucking

Well Operator: SM ENERGY COMPANY

Well Name: CAPSTICK 2-4H

Field Name: FT. BUFORD

Well File #: 22816

Date Incident: 3/21/2015 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 152 **Rng:** 104 **Sec:** 4 **Qtr:**

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
13745 55th St NW, Williston, ND 58801
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	5	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

minimal

Areal Extent:

Potential Environmental Impacts:

minimal, Spill has been remediated

Action Taken or Planned:

inspect equipment prior to start up

Wastes Disposal Location: dishon disposal

Agencies Involved:

Updates

Date: 3/23/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.