

# Oil Field Environmental Incident Summary

**Incident:** 20150329060231      **Date/Time of Notice:** 03/29/2015 06:02

**Responsible Party:** Petro Harvester Operating Company, LLC

**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:** HARMS 21-9

**Field Name:** FLAXTON

**Well File #:** 10898

**Date Incident:** 3/28/2015      **Time Incident:** 07:45

**Facility ID Number:**

**County:** BURKE

**Twp:** 163

**Rng:** 91

**Sec:** 21

**Qtr:** NE SE

**Location Description:**

**Submitted By:** Gary Watson

**Received By:**

**Contact Person:** Mark Bonnie  
5160 TENNYSON PARKWAY  
SUITE 3000 E  
PLANO, TX 75024

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Barrels	10	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Minimal

**Areal Extent:**

**Potential Environmental Impacts:**

Minimal affect to facility soil.

**Action Taken or Planned:**

NDIC Inspector Jim Potts was contacted. Released oil will be vacuumed up and affected facility soil scraped up, collected and hauled to an approved disposal facility.

**Wastes Disposal Location:** Approved disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 3/30/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a treater leak, remained on location within the diking according to the report. NDIC retains oversight.