

Oil Field Environmental Incident Summary

Incident: 20150416170430 **Date/Time of Notice:** 04/16/2015 17:04

Responsible Party: SLAWSON EXPLORATION COMPANY, INC.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: ZULU 1-21H

Field Name: VAN HOOK

Well File #: 18199

Date Incident: 4/16/2015 **Time Incident:** 00:02

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 92

Sec: 28

Qtr:

Location Description: GBS #2, a site about 530 feet to the east.

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1764 Feet

Distance Nearest Water Well: 1765 Feet

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Gallons	28	Gallons		

Brine

Other

Description of Other Released Contaminant:

.....

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none...

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

site cleaned up, impacted soil removed, .

Wastes Disposal Location: disposed of properly at a licensed facility

Agencies Involved:

Updates

Date: 4/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pump leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.