

# Oil Field Environmental Incident Summary

**Incident:** 20150418111448      **Date/Time of Notice:** 04/18/2015 11:14

**Responsible Party:** OXY USA INC.

**Well Operator:** OXY USA INC.

**Well Name:** STATE 11-32H

**Field Name:** WILLMEN

**Well File #:** 16211

**Date Incident:** 4/17/2015      **Time Incident:** 11:30

**Facility ID Number:**

**County:** DUNN

**Twp:** 143

**Rng:** 97

**Sec:** 32

**Qtr:**

**Location Description:**

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
5 GREENWAY PLAZA STE 110  
HOUSTON, TX 77046-0506

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1.5	Barrels	1	Barrels	1.5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 5/26/2015

**Clean Up Concluded:** 4/24/2015

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

The packing has been replaced, Rud was immediately dispatched to recover all standing liquids, a roustabout crew is scheduled to remove any contaminated surface material.

**Wastes Disposal Location:** Chimney Butte

**Agencies Involved:**

**Updates**

---

**Date:** 4/20/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained within the dikes on location. NDIC retains oversight.