

# Oil Field Environmental Incident Summary

**Incident:** 20150420160053      **Date/Time of Notice:** 04/20/2015 16:00

**Responsible Party:** ENDURO OPERATING, LLC

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** SNOWCOVER 43-19 SWD

**Field Name:** SNOWCOVER

**Well File #:** 11719

**Date Incident:** 4/17/2015      **Time Incident:** 19:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 147

**Rng:** 101

**Sec:** 19

**Qtr:**

**Location Description:**

**Submitted By:** Scott Hunskor

**Received By:**

**Contact Person:** Scott Hunskor  
777 MAIN STREET  
SUITE 800  
FORT WORTH, TX 76102

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Barrels	10	Barrels	10	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/19/2015

**Clean Up Concluded:** 4/20/2015

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Shut truck down, load from tank to get to acceptable level, load fluid inside of dike, wash inside of dike with water.

**Wastes Disposal Location:** Nuverra

**Agencies Involved:**

**Updates**

---

**Date:** 4/20/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location within the diking. NDIC retains oversight.