

Oil Field Environmental Incident Summary

Incident: 20150502103522 **Date/Time of Notice:** 05/02/2015 10:35

Responsible Party: SLAWSON EXPLORATION COMPANY, INC.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: ZULU 1-21H

Field Name: VAN HOOK

Well File #: 18199

Date Incident: 5/1/2015 **Time Incident:** 12:12

Facility ID Number:

County: MOUNTRAIL

Twp: 152 **Rng:** 92 **Sec:** 28 **Qtr:**

Location Description: 650 feet to the east is a Pelican Gathering Booster Station, spill occurred there. GBS #2.

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1700 Feet

Distance Nearest Water Well: 1700 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

.....

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

.....

Potential Environmental Impacts:

none

Action Taken or Planned:

tanks shut in, oil cleaned up, soil remediated/removed.

Wastes Disposal Location: licensed disposal facility.

Agencies Involved:

Updates

Date: 5/4/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation's boundaries. Forward to BIA/Tribal authorities.