

# Oil Field Environmental Incident Summary

**Incident:** 20150504085314      **Date/Time of Notice:** 05/04/2015 08:53  
**Responsible Party:** WHITING OIL AND GAS CORPORATION  
**Well Operator:** WHITING OIL AND GAS CORPORATION  
**Well Name:** ANDERSON 152-103-21-16-1H  
**Field Name:** GLASS BLUFF      **Well File #:** 24303  
**Date Incident:** 5/3/2015      **Time Incident:** 08:00      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 152      **Rng:** 103      **Sec:** 21      **Qtr:** SE SW  
**Location Description:**

**Submitted By:** Corissa Zimmer      **Received By:**  
**Contact Person:** Corissa Zimmer  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile  
**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels	1	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None noted.

**Areal Extent:**

**Potential Environmental Impacts:**

None noted.

**Action Taken or Planned:**

Whiting will put a high level float in the sump, so that the sump will function properly in the event of a release.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 5/4/2015    **Status:** Reviewed - Assigned to Other Agency    **Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.