

Oil Field Environmental Incident Summary

Incident: 20150519141725 **Date/Time of Notice:** 05/19/2015 14:17

Responsible Party: Crestwood Crude Transportation, LLC

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ANTELOPE 1-23H2

Field Name: ELM TREE

Well File #: 22820

Date Incident: 5/18/2015 **Time Incident:** 21:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 94

Sec: 23

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Joseph Hoffart
PO BOX 646
Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/5/2015

Clean Up Concluded: 6/3/2015

Risk Evaluation:

fire

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

It is both Crestwood and CLR's policy that haulers must be at their truck during offload, which this driver was not at the time of the release. The driver was reprimanded and will not be hauling on CLR locations. This policy will be revisited by Crestwood with their haulers.

Wastes Disposal Location: Newalta

Agencies Involved: Sam Skurupey, NDIC inspector

Updates

Date: 5/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.