

Oil Field Environmental Incident Summary

Incident: 20150519161303 **Date/Time of Notice:** 05/19/2015 16:13

Responsible Party: Heat Waves Hot Oil Service

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HARMS 2-32H

Field Name: ELM TREE

Well File #: 22817

Date Incident: 5/19/2015 **Time Incident:** 08:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 93

Sec: 32

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Debra Ballenger
10446 1st Street South
Killdeer, ND 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	5	Barrels	5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 5/28/2015

Clean Up Concluded: 5/23/2015

Risk Evaluation:

Splash from fluid release

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Standing fluid sucked up. Contaminated gravel and soil recovery in progress. Incident is still under investigation by Heat Waves and CLR.

Wastes Disposal Location: TBD

Agencies Involved: Sam Skurupey, NDIC inspector

Updates

Date: 5/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.