

# Oil Field Environmental Incident Summary

**Incident:** 20150528031259      **Date/Time of Notice:** 05/28/2015 03:12

**Responsible Party:** CYPRESS ENERGY PARTNERS - BAKKEN, LLC

**Well Operator:** CYPRESS ENERGY PARTNERS - BAKKEN, LLC

**Well Name:** ASHTON DAWN SWD 1

**Field Name:** STANLEY

**Well File #:** 90208

**Date Incident:** 5/25/2015      **Time Incident:** 1847

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 155

**Rng:** 91

**Sec:** 15

**Qtr:**

**Location Description:** Salt water disposal

**Submitted By:** David LaZelle

**Received By:**

**Contact Person:** David LaZelle  
5727 S. LEWIS AVENUE,  
SUITE 500  
TULSA, OK 74105

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	3	Barrels		
<b>Brine</b>	5	Barrels	5	Barrels		

**Other**

**Description of Other Released Contaminant:**

none

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Attendant will perform walk around after all work in or around tank battery. And attendants have been reminded that a site walk around is to be done every 3 hours as well as at the beginning and end of shift.

**Wastes Disposal Location:** All fluid was returned to the system on site.

**Agencies Involved:**

**Updates**

---

**Date:** 5/28/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.