

# Oil Field Environmental Incident Summary

**Incident:** 20150528122305      **Date/Time of Notice:** 05/28/2015 12:23

**Responsible Party:** SM ENERGY COMPANY

**Well Operator:** SM ENERGY COMPANY

**Well Name:** ERRMU 2-18

**Field Name:** ROUGH RIDER

**Well File #:** 7483

**Date Incident:** 5/20/2015      **Time Incident:** 10:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 145      **Rng:** 100      **Sec:** 18      **Qtr:**

## Location Description:

**Submitted By:** Luke Studer

**Received By:**

**Contact Person:** Luke Studer  
PO BOX 7168  
BILLINGS, MT 59103-7168

**General Land Use:** Badlands Terrain

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>					0	barrels
<b>Brine</b>					0	barrels
<b>Other</b>	5	Gallons			0	barrels

## Description of Other Released Contaminant:

5 gallons fluid and 20 cubic ft gas released.

**Inspected:**

**Written Report Received:** 3/9/2016

**Clean Up Concluded:** 5/1/2015

## Risk Evaluation:

None.

## Areal Extent:

Unknown

**Potential Environmental Impacts:**

N/A.

**Action Taken or Planned:**

The line has been repaired.

**Wastes Disposal Location:** Contaminated soil was hauled to an approved disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 5/28/2015    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to pipeline leak, got off location. Followup is necessary.

---

**Date:** 6/15/2015    **Status:** Inspection

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:** 5.00 gallons

**Updated Other Contaminant** 5 gallons fluid and 10 cubic feet gas

**Notes:**

NDDH inspector arrived onsite at 9:30am. Weather was sunny with wind out of the south at 20 mile/hour. The area of impact is located south of the pad about 1000ft. It has been scraped and cleaned up. Area surrounding the site is badlands terrain and no water way was impacted by the spill. Due to rain in the last two days, a puddle of water was standing in the location where the spill clean-up occurred. Conducted a chloride strip test on the standing water located on the location and it came back as less than 31ppm. No additional follow-up required.