

Oil Field Environmental Incident Summary

Incident: 20150612155040

Date/Time of Notice: 06/12/2015 15:50

Responsible Party: unknown

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 6/8/2015

Time Incident: 00:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 96

Sec: 25

Qtr: NE NW

Location Description:

Submitted By: Derek Enderud

Received By:

Contact Person: unknown unknown

unknown

unknown, ND 00000

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Topsoil

Action Taken or Planned:

Contaminated material was scraped up and is being taken to PDI. We worked with the landowner until he was satisfied. Topsoil was hauled back to the site and re-spread. Field inspector Samuel Skurupey was contacted via phone.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/15/2015 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This incident was called in to the party who then submitted the report. The incident involved an apparent illegal dump of salt water across the road from a wellpad belonging to the submitter's company. The company was unable to determine who was responsible for the discharge, and so worked with the landowner to get it cleaned up themselves. On Friday, 7 loads of impacted soil were removed to Prarie Hills Disposal. Follow-up required.

Date: 8/11/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:47 p.m. The weather was sunny, 81°F, with the wind from the southeast 10-15 mph. The area is across from the well pad in the cropland to the south. It followed a drainage area that is cropped. The area has been scraped up, and soil has been placed in the area. The field has been harvested. 47.26313, -102.91712