

# Oil Field Environmental Incident Summary

**Incident:** 20150615083127      **Date/Time of Notice:** 06/15/2015 08:31

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** SORKNESS STATE 34X-36

**Field Name:** SORKNESS

**Well File #:** 18959

**Date Incident:** 6/14/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 157

**Rng:** 93

**Sec:** 36

**Qtr:**

**Location Description:**

**Submitted By:** Scot Richardson

**Received By:**

**Contact Person:** Scot Richardson  
P.O Box 6506  
Williston, ND 58802

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	20	Gallons	20	Gallons		
<b>Brine</b>	3	Barrels	3	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Fire tube will be replaced and clean-up crews will collect the free liquids and return them to the tanks. The impacted soils will be collected and transported to an approved disposal facility.

**Wastes Disposal Location:** MBI saltwater disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 6/15/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to treater leak, remained on location within the diking, according to the report. NDIC retains oversight.