

Oil Field Environmental Incident Summary

Incident: 20150615084810 **Date/Time of Notice:** 06/15/2015 08:48

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: SNOWCOVER 43-19 SWD

Field Name: SNOWCOVER

Well File #: 11719

Date Incident: 6/13/2015 **Time Incident:** 03:30

Facility ID Number:

County: MCKENZIE

Twp: 147

Rng: 101

Sec: 19

Qtr:

Location Description:

Submitted By: Rodney Conway

Received By:

Contact Person: Rodney Conway
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	440	Barrels			400	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/26/2016

Clean Up Concluded: 6/17/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

smoke residue

Action Taken or Planned:

Clean up facility and rebuild with new tanks,etc

Wastes Disposal Location: Landfill

Agencies Involved: Local Fire Department Local Law Enforcement. Mckenzie County Emergency Manager

Updates

Date: 6/15/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to NDIC, most fluid evaporated during fire.

Date: 6/15/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location, according to the report. NDIC retains oversight. Due to volume released, requested information from NDIC inspector.