

Oil Field Environmental Incident Summary

Incident: 20150615084918 **Date/Time of Notice:** 06/15/2015 08:49

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: DOHMSTRIECH 15B-20HN

Field Name: MUSTA

Well File #: 29624

Date Incident: 6/13/2015 **Time Incident:** 08:00

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 99

Sec: 20

Qtr:

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Barrels	10	Barrels		

Description of Other Released Contaminant:

Drill Cuttings

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

minimal

Areal Extent:

10X20

Potential Environmental Impacts:

Minimal

Action Taken or Planned:

Containment bins will be placed no closer than 10' feet from the dike

Wastes Disposal Location: Secure Energy

Agencies Involved:

Updates

Date: 6/15/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location within the diking, according to the report. NDIC retains oversight.