

# Oil Field Environmental Incident Summary

**Incident:** 20150618142842      **Date/Time of Notice:** 06/18/2015 14:28  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** HARLEY 31-2TFH  
**Field Name:** BLUE BUTTES      **Well File #:** 26222  
**Date Incident:** 6/18/2015      **Time Incident:** 07:15      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 151      **Rng:** 95      **Sec:** 2      **Qtr:**  
**Location Description:**

**Submitted By:** TIM HOMISTON      **Received By:**  
**Contact Person:** DONNA WILLIAMS  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - On Facility Site      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

No spill occurred

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

Minimal risk to personnel, environment, and equipment

**Areal Extent:**

Fire contained to the cord

**Potential Environmental Impacts:**

Minimal to none

**Action Taken or Planned:**

Replaced cord and power unit. Evaluate both for integrity

**Wastes Disposal Location:** No waste generated

**Agencies Involved:**

**Updates**

---

**Date:** 6/18/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Fire on location. Nothing released off location according to the report. NDIC retains oversight.