

Oil Field Environmental Incident Summary

Incident: 20150630101617 **Date/Time of Notice:** 06/30/2015 10:16

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: GERALD HALE 33-28H

Field Name: SPOTTED HORN

Well File #: 20556

Date Incident: 6/30/2015 **Time Incident:** 03:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 94

Sec: 33

Qtr:

Location Description:

Submitted By: Robert Raup

Received By:

Contact Person: Robert Raup
10471 One A Street SW
Killdeer, ND 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

*** There was no release. This report is being generated because there was a fire on location.***

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Very low risk at this time.

Areal Extent:

Treater building was inside of steel containment.

Potential Environmental Impacts:

No potential for environmental impacts.

Action Taken or Planned:

The fire was extinguished by the Fire Department. Planned future actions are to determine a root cause of the fire once the treater has cooled down.

Wastes Disposal Location: There is no environmental waste to dispose of as there was no release. Parts of the treater affected by the fire will be removed and disposed of accordingly.

Agencies Involved: Local Fire Department
MHA Energy

Updates

Date: 6/30/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report there was no release. The report was being generated because of a fire on location, within dike. NDIC retains oversight.