

Oil Field Environmental Incident Summary

Incident: 20150712131943 **Date/Time of Notice:** 07/12/2015 13:19

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL SECTION 30 NWNE CENTRAL FACILITY

Field Name: PARSHALL

Well File #:

Date Incident: 7/11/2015 **Time Incident:** 20:26 **Facility ID Number:** 229261-01

County: MOUNTRAIL **Twp:** 152 **Rng:** 90 **Sec:** 30 **Qtr:** NW NE

Location Description: 6 bbls of oil onsite with 2 bbls of oil offsite. The affected area offsite will be determined more after grassland vegetation has been clipped, removed and surveyed.

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	Barrels	6	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/8/2015

Clean Up Concluded: 8/21/2015

Risk Evaluation:

N/A

Areal Extent:

5ft x 100 ft - This area will be surveyed and more defined details in NDIC followup report

Potential Environmental Impacts:

N/A

Action Taken or Planned:

A hydrovac was used to removed standing liquids and top layer of soil onsite. Offsite vegetation will be clipped and removed and EOG is awaiting a call back from landowner to discuss further cleanup actions needed and will proceed after discussions made with landowner. Once flowback operations cease the tanks will be removed and further cleanup will be completed underneath and behind the tanks.

Wastes Disposal Location: Clean Harbors, Sawyer, ND

Agencies Involved: TAT and MHA

Updates

Date: 7/13/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident summary, release impacted areas off location. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.