

Oil Field Environmental Incident Summary

Incident: 20150714132751 **Date/Time of Notice:** 07/14/2015 13:27

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: GARY LEE 31-30H

Field Name: ALEXANDRIA

Well File #: 26475

Date Incident: 7/13/2015 **Time Incident:** 19:10

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 100

Sec: 31

Qtr: SW SE

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The hose was repaired. A vacuum truck was called and fluid was removed. The area will be bioremediated.

Wastes Disposal Location: Production tank on site.

Agencies Involved:

Updates

Date: 7/14/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.