

# Oil Field Environmental Incident Summary

**Incident:** 20150716103547      **Date/Time of Notice:** 07/16/2015 10:35

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** REDMOND 27-2932H

**Field Name:** CLEAR WATER

**Well File #:** 22931

**Date Incident:** 7/15/2015      **Time Incident:** 11:05

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 157

**Rng:** 89

**Sec:** 29

**Qtr:** NW NE

**Location Description:**

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Person:** Danielle Dupay  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	10	Barrels	10	Barrels	10	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/8/2015

**Clean Up Concluded:** 7/17/2015

**Risk Evaluation:**

N/A

**Areal Extent:**

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

The spill was contained within lined tank containment. The lined containment was flushed with freshwater and residual water removed. Repairs or replacement of tank will be determined once tank has been removed from containment for inspection.

**Wastes Disposal Location:** SWD

**Agencies Involved:**

**Updates**

---

**Date:** 7/16/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.