

# Oil Field Environmental Incident Summary

**Incident:** 20150717124509      **Date/Time of Notice:** 07/17/2015 12:45  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** SEQUOIA 14-9MBH  
**Field Name:** HAWKEYE      **Well File #:** 26599  
**Date Incident:** 7/16/2015      **Time Incident:** 13:30      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 152      **Rng:** 95      **Sec:** 9      **Qtr:** SW SE  
**Location Description:**

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile  
**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - On Constructed Well Site      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

There was no release.

**Inspected:**      **Written Report Received:**      **Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Not applicable

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

The fire was extinguished and the brake was repaired.

**Wastes Disposal Location:** NA

**Agencies Involved:**

**Updates**

---

**Date:** 7/20/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Fire, remained on location according to the report. NDIC retains oversight.