

Oil Field Environmental Incident Summary

Incident: 20150718170036 **Date/Time of Notice:** 07/18/2015 17:00

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: DWIGHT LUDWIG 13-24H

Field Name: WRITING ROCK

Well File #: 26207

Date Incident: 7/15/2015 **Time Incident:** 14:30

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 101

Sec: 13

Qtr: NE NW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Cleanup was started. Will arrange a meeting with the trucking company to prevent future incidents. Remediation of the area to start after cleanup is complete.

Wastes Disposal Location: TDB

Agencies Involved:

Updates

Date: 7/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.