

Oil Field Environmental Incident Summary

Incident: 20150719132201 **Date/Time of Notice:** 07/19/2015 13:22

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: FRISCO 3-31H

Field Name: GLASS BLUFF

Well File #: 29302

Date Incident: 7/18/2015 **Time Incident:** 13:30

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 31 **Qtr:**

Location Description:

Submitted By: NATE STANHOPE

Received By:

Contact Person: NATE STANHOPE
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels	0.5	Barrels	0.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/3/2016

Clean Up Concluded: 7/24/2015

Risk Evaluation:

N/A

Areal Extent:

110' x 75' area of wheat was misted.

Potential Environmental Impacts:

Wheat and location soil.

Action Taken or Planned:

All oil on location has been cleaned up and removed. The landowner was notified and messages have been left for the leasee to discuss clean-up options for his lightly misted wheat. Will complete clean-up activities as soon as permission is granted.

Wastes Disposal Location: A licensed disposal facility.

Agencies Involved: Notified Bill Suess NDDH by email on 7/18/15 at 4:37 PM MT

Updates

Date: 7/20/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Oil sprayed off location, follow-up needed.

Date: 7/21/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:15 p.m. The weather was sunny, 79°F, with the wind from the southeast 10-15 mph. The spray occurred on the east side of pad, just east of the flare. Dirt work has been done between the cropland and gravel on pad. The wheat that is stained is still standing, could not see any staining on soil in field. More follow-up needed to check on clean-up progress. 46.89505, -102.86685