

Oil Field Environmental Incident Summary

Incident: 20150720125023 **Date/Time of Notice:** 07/20/2015 12:50

Responsible Party: SLAWSON EXPLORATION COMPANY, INC.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: WALLEYE (FEDERAL) 4-12-11TF2H

Field Name: SANISH

Well File #: 26268

Date Incident: 7/19/2015 **Time Incident:** 20:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 92

Sec: 7

Qtr:

Location Description: Part cultivated, part "rough" sloped rangelands. Grassy and weedy...

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1600 Feet

Distance Nearest Water Well: 1600 Feet

Type of Incident: Pump Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	1.8	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

.....

Inspected:

Written Report Received: 4/18/2016

Clean Up Concluded: 7/23/2015

Risk Evaluation:

minimal, oil will be cleaned up, removed.

Areal Extent:

The wind was blowing making the spray get off location for approximately 100 ft. X 20'

Potential Environmental Impacts:

Oily soil, which will be removed.

Action Taken or Planned:

Make sure this part on the rest of our pumps are inspected and replaced.

Wastes Disposal Location: State approved oil field disposal facility.

Agencies Involved:

Updates

Date: 7/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release is due to a pump leak. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.