

Oil Field Environmental Incident Summary

Incident: 20150726075048 **Date/Time of Notice:** 07/26/2015 07:50
Responsible Party: FIDELITY EXPLORATION & PRODUCTION COMPANY
Well Operator: FIDELITY EXPLORATION & PRODUCTION COMPANY
Well Name: HELEN 11-15H-22
Field Name: SANISH **Well File #:** 21525
Date Incident: 7/25/2015 **Time Incident:** 09:00 **Facility ID Number:**
County: MOUNTRAIL **Twp:** 154 **Rng:** 92 **Sec:** 15 **Qtr:**

Location Description:

Submitted By: Edward Pottorff **Received By:**
Contact Person: Edward Pottorff
1801 CALIFORNIA STREET
SUITE 2500
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	2.7	Barrels	2.7	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/6/2015 **Clean Up Concluded:** 7/25/2015

Risk Evaluation:

No immediate risks were identified.

Areal Extent:

Potential Environmental Impacts:

Only the facility soil and gravel in the vicinity of the pumping unit were affected.

Action Taken or Planned:

The pumping unit and affected gravel will be pressure washed and the associated liquids collected and disposed at a licensed facility. If affected soils remain, they will be excavated and hauled off site to a licensed disposal facility and replaced with clean soil.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/27/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Suess, Bill

Updated Oil Volume: 3.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release contained within well pad. NDIC Oil and Gas retains oversight.